

| | Teile-Nr. | Bestell-Nr. | Stück je Maschine | | Teile-Nr. | Bestell-Nr. | Stück je Maschine |
|-------------------------|-----------|-------------|-------------------------|--------------------------|-----------|-------------|-------------------------|
| Schraubhandgriff | 1 | P26C/1 | 1 | O-Ring 12x1,5 | 54 | P26C/54 | 1 |
| Einlegemutter M10 | 2 | P26C/2 | 1 | Oberschale | 55 | P26C/55 | 1 |
| Klemmring | 3 | P26C/3 | 1 | Linsenschraube 3,5x20 | 56 | P26C/56 | 4 |
| Kreuzgriffschraube | 4 | P26C/4 | 1 | Kugel Ø 4mm | 57 | P26C/57 | 1 |
| Sechskantmutter M5 | 5 | P26C/5 | 1 | Rastenfeder | 58 | P26C/58 | 1 |
| Anschlagstange | 6 | P26C/6 | 1 | Senkschraube M5x8 | 59 | P26C/59 | 1 |
| Tülle | 7 | P26C/7 | 1 | Zylindergehäusedichtung | 60 | P26C/60 | 1 |
| Manschette | 8 | P26C/8 | 1 | Kurbel | 61 | P26C/61 | 1 |
| Futterhülse | 9 | P26C/9 | 1 | Rillenkugellager | 62 | P26C/62 | 1 |
| Sprengring | 10 | P26C/10 | 2 | Kurbelrad | 63 | P26C/63 | 1 |
| Haltering | 11 | P26C/11 | 1 | Axialscheibe | 64 | P26C/64 | 1 |
| Futerring | 12 | P26C/12 | 1 | Zylinderlager | 65 | P26C/65 | 2 |
| Anschlagring | 13 | P26C/13 | 1 | Kegelritzelrad | 66 | P26C/66 | 1 |
| Feder | 14 | P26C/14 | 1 | Rillenkugellager | 67 | P26C/67 | 1 |
| Schaltfeder | 15 | P26C/15 | 1 | Getriebepatte | 68 | P26C/68 | 1 |
| Hülse | 16 | P26C/16 | 1 | Kupferdichtring M5 | 69 | P26C/69 | 6 |
| Kugel Ø 7mm | 17 | P26C/17 | 2 | Zylinderschraube M5x16 | 70 | P26C/70 | 6 |
| Futter | 18 | P26C/18 | 1 | V-Ring | 71 | P26C/71 | 1 |
| Zylinderschraube M5x20 | 19 | P26C/19 | 4 | O-Ring 18x2 | 72 | P26C/72 | 1 |
| Bohrkopf | 20 | P26C/20 | 1 | V-Ringscheibe | 73 | P26C/73 | 1 |
| Bohrkopfdichtung | 21 | P26C/21 | 1 | Lagergummi | 74 | P26C/74 | 1 |
| Doppelabstreifer | 22 | P26C/22 | 1 | Rillenkugellager | 75 | P26C/75 | 1 |
| Döpper | 23 | P26C/23 | 1 | Sicherungsring | 76 | P26C/76 | 1 |
| Bundgleitlager | 24 | P26C/24 | 1 | Anker | 77 | P26C/77 | 1 |
| O-Ring 23x5 | 25 | P26C/25 | 2 | Rillenkugellager | 78 | P26C/78 | 1 |
| Quadring | 26 | P26C/26 | 1 | Lagergummi | 79 | P26C/79 | 1 |
| Bohrspindel | 27 | P26C/27 | 1 | Linsenkopfschraube 4x48 | 80 | P26C/80 | 2 |
| Gleitlager | 28 | P26C/28 | 1 | Luftleitflansch | 81 | P26C/81 | 1 |
| Sicherungsring | 29 | P26C/29 | 1 | Feldpaket | 82 | P26C/82 | 1 |
| Bremsring | 30 | P26C/30 | 1 | Motorgehäuse | 83 | P26C/83 | 1 |
| Kupplungsfeder | 31 | P26C/31 | 1 | Linsenschraube 3,5x30 | 84 | P26C/84 | 2 |
| Haltestift | 32 | P26C/32 | 2 | Umschalthebel | 85 | P26C/85 | 1 |
| Nadelrolle | 33 | P26C/33 | 3 | Linsensenkschraube M4x10 | 86 | P26C/86 | 1 |
| Sicherheitskupplung | 34 | P26C/34 | 1 | Typenschild | 87 | P26C/87 | 1 |
| Schaltklaue | 35 | P26C/35 | 1 | Kohlehalter | 88 | P26C/88 | 2 |
| Sicherungsring | 36 | P26C/36 | 1 | Linsenkopfschraube 3x10 | 89 | P26C/89 | 4 |
| O-Ring 43x4 | 37 | P26C/37 | 1 | Kohlebürste | 90 | P26C/90 | 2 |
| Lagerring | 38 | P26C/38 | 1 | Motordeckel | 91 | P26C/91 | 1 |
| Dämpfscheibe | 39 | P26C/39 | 3 | Linsenkopfschraube 4x14 | 92 | P26C/92 | 6 |
| Sprengring | 40 | P26C/40 | 2 | DUSS-Aufkleber | 93 | P26C/93 | 2 |
| Zylinder | 41 | P26C/41 | 1 | Kondensator | 94 | P26C/94 | 1 |
| Schläger | 42 | P26C/42 | 1 | Dämpfer-Zylindergehäuse | 95 | P26C/95 | 1 |
| Kolbenring | 43 | P26C/43 | 1 | Schalter | 96 | P26C/96 | 1 |
| Kolbenring | 44p | P26C/44p | 1 | Schalterschutz | 97 | P26C/97 | 1 |
| Kolbenbolzen | 45 | P26C/45 | 1 | Dämpfer-Motorgehäuse | 98 | P26C/98 | 1 |
| Federring | 46 | P26C/46 | 2 | Schalterhandgriff | 99 | P26C/99 | 1 |
| Kolben | 47 | P26C/47 | 1 | Abstandsbuchse | 100 | P26C/100 | 4 |
| Pleuel | 48 | P26C/48 | 1 | Linsenschraube 5x30 | 101 | P26C/101 | 4 |
| Nadelhülse | 49 | P26C/49 | 1 | Linsenkopfschraube 4x20 | 102 | P26C/102 | 2 |
| Zylindergehäuse | 50 | P26C/50 | 1 | Kabelschutzschlauch | 103 | P26C/103 | 1 |
| Linsenkopfschraube 4x25 | 51 | P26C/51 | 6 | Kabelklemme | 104 | P26C/104 | 1 |
| Zylinderring 5x10 | 52 | P26C/52 | 1 | Kabel mit Stecker | 105 | P26C/105 | 1 |
| Schaltwelle | 53 | P26C/53 | 1 | | | | |

DUSS

Kombihammer P 26 C

